




**FIG. 1**




**FIG. 2**




**FIG. 3**






**FIG. 4A**




**FIG. 4B**


**FIG. 5**




**FIG. 6**




**FIG. 7**




**FIG. 8**




**FIG. 9**



**FIG. 10**



**FIG. 11**



**FIG. 12**

Search Criteria	
PMA Number:	LMOS TTN: _____
Status:	Specify Sort Order?
NPA WC:	Dist: _____
Manager:	_____
Supervisor:	_____
Tech:	_____
Work By: From:	To: _____
Pending: From:	To: _____
Dispatch: From:	To: _____
Complete: From:	To: _____
Work Address:	_____
Work Description:	_____
FST Narrative:	_____
Disp Code:	_____
Priority:	IST: _____ Work Code: _____
Auth #:	Type: _____
Cable:	Pair: _____

**FIG. 13**

Search Criteria	
PMA Number:	<input type="text"/>
Status:	<input type="text"/>
NPA WC:	<input type="text"/>
Manager:	<input type="text"/>
Supervisor:	<input type="text"/>
Tech:	<input type="text"/>
Work By: From:	<input type="text"/>
Pending: From:	<input type="text"/>
Dispatch: From:	<input type="text"/>
Complete: From:	<input type="text"/>
Work Address:	<input type="text"/>
Work Description:	<input type="text"/>
FST Narrative:	<input type="text"/>
Disp Code:	<input type="text"/>
Priority:	<input type="text"/>
Auth #:	<input type="text"/>
Cable:	<input type="text"/>
N:	<input type="text"/>
Sort Order:	<input type="text"/>
PMA	<input type="text"/>
NPA	<input type="text"/>
Wire Center	<input type="text"/>
District	<input type="text"/>
Manager	<input type="text"/>
Supervisor	<input type="text"/>
Technician	<input type="text"/>
Priority	<input type="text"/>
Status	<input type="text"/>
Authorization	<input type="text"/>
Work By Date	<input type="text"/>
Pending Date	<input type="text"/>
Dispatch Date	<input type="text"/>
Complete Date	<input type="text"/>
TTN	<input type="text"/>
Type	<input type="text"/>
Work Address	<input type="text"/>
Order?	<input type="text"/>

**FIG. 14**

PMA Number	Auth NPA	Wire Ctr	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
<b>990603181</b>	<b>404</b>	<b>283</b>	<b>1773</b>	D	<b>6/10/00</b>	<b>6/10/00</b>	<b>6/10/00</b>	
990603322	404	283	1773		6/10/00	6/10/00	6/10/00	
990603187	404	284	1773		6/10/00	6/10/00	6/10/00	
990601004	404	285	1773		6/3/00	6/3/00	6/3/00	
990603524	404	285	1773		6/10/00	6/10/00	6/10/00	
Manager:	Smith	Technician:	Jones					
IST:	DPO	Line Records:	404283RTAP01	L/MOS TIN:	1134			
Pre-Assign:	Y	Priority:	5	Estimated Time:	8	Actual Time:		
Additional Tasks:	N	Task:	1 of 1	# Cable Recs:	0			
FST Narrative:	ETA 0747A	Work Address:	Main Street Work Center	Work Description:	Run Helium on Buried Cable to Locate Air Leak			

**N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q - Quit**

FIG. 15

PMA Number	Auth	NPA	Wire Cir	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
0000603191	404	283	1773	D		Notes	6/10/00	6/10/00	

**FIG. 16**

PMA Number	Auth	NPA	Wire Ctr	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
990603181	404	283	1773	D	6/10/00	6/10/00	6/10/00	6/10/00	6/10/00
990603322	404	283	1773		6/10/00	6/10/00	6/10/00	6/10/00	6/10/00
990603187	404	284	1773		6/10/00	6/10/00	6/10/00	6/10/00	6/10/00
990601004	404	285	1773		6/3/00	6/3/00	6/3/00	6/3/00	6/3/00
990603524	404								6/10/00

**PMA Cable Records**

Manager:	<u>Cable</u>	<u>Low Pair</u>	<u>High Pair</u>
Technician	1612	76	100
IST: DPC			1134
Pre-Assign			Actual Time:
Additional			
FST Narrat			
Work Addi			
Work Descri			

N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit

**FIG. 17**

PMA Number	Auth NPA	Wire Ctr	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
990603181	404	283	1773	D	<b>6/10/00</b>	<b>6/10/00</b>	<b>6/10/00</b>	
990603322	404	283	1773		6/10/00		6/10/00	
990603187	404	284	1773		6/10/00		6/10/00	
990601004	404	285	1773		6/3/00		6/3/00	
990603524	404	285	1773		6/10/00		6/10/00	
								Other Messages

Created by: Smith  
Dispatch Time: 0747      Complete Time: 1200  
LMOS Return Message: 0055501 Created TN 205221RTPPS08  
LMOS Time Stamp: 06/01/00 07:15:37 pkmcryk

FST Narrative: ETA 0747A
Work Address: Main Street Work Center
Work Description: Run Helium on Buried Cable to Locate Air Leak

N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit

**FIG. 18**

<u>PMA Number</u>	<u>IST:</u> pao	<u>Dispatch Data</u>	<u>Complete Date</u>
990603181	107 202 404	1772 1772	06/01/00 06/01/00 6/10/00
990602222	302		06/01/00 6/10/00
<u>PMA Number</u>	<u>Tech</u>	<u>IST</u>	<u>Work Address</u>
9906		pao	123 Main ST.
9906			
9906			
00060183			

**N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit**

**FIG. 19**

PMA Number	Auth NPA	Wire Ctr	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
990603181	404	283	1773	D	6/10/00	6/10/00	6/10/00	6/10/00
990603322	404	283	1773		6/10/00	6/10/00	6/10/00	6/10/00
990603187	404	284	1773		6/10/00	6/10/00	6/10/00	6/10/00
990601004	404	285	1773		6/3/00	6/3/00	6/3/00	6/3/00
990603524	404	285	1773		6/10/00	6/10/00	6/10/00	6/10/00

Manager:	Smith	Supervisor:	Jones
Technician:	9999999999		

IST:	DPO	Line Records:	404283RTAP01	LMOS ITIN:	1134
Pre-Assign:	Y	Priority:	5	Estimated Time:	8
Additional Tasks:	N	Task:	1 of 1	# Cable Recs:	0
FST Narrative:	ETA 0747A				
Work Address:	Main Street Work Center				
Work Description:	Run Helium on Buried Cable to Locate Air Leak				

**N - Notes, C - Cable, M - Messages, D - Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit**

**FIG. 20**

PMA Number	Auth.	NPA	Wire Ctr	Dist Num	S	Pending Date	Work By Date	Dispatch Date	Complete Date
990603181	404	283	D	1773		6/10/00	6/10/00	6/10/00	
990603322	404	283	D	1773		6/10/00	6/10/00	6/10/00	
990603187	40								
990601004	40								
990603524	40								

Enter E-Mail Recipient's Address

Valid User ID's

ID	Name	Phone	Supy
Aainpq1	CASH, JOHN	(555)-8268	NONE
Gdownfu	JONES, GEORGE	(555)555-1234	NONE
Keppbyz	NELSON, WILL	(555)555-7890	ocziua
Jjbiq1	ROBBINS, MARTY	(555)555-5561	mispnc
Nhtapql	WILLIAMS, H.	(555)555-3456	lpbyiv
Pmcexak1	WYNETTE, T.	(555)555-3456	pbbufs

N - Notes, C - Comments, D - Dispatched, P - Pending, S - Suspended, W - Worked

-Quit

**FIG. 21**

PMA PENDING DATA	
ADD	
NPA:	Wire Center:
	Dist #:
Maintenance Center: Type:	Pre-Assign:
Auth:	Pre-Est:
Additional Tasks:	Task: 1 of 1
Work Code:	Pending Date:
Work Address:	Dispatch Date:
Work Desc:	Work By Date:
	Mgr: Supv: Clear Data? Yes Priority: 5 Tech:

**FIG. 22**

<input type="button" value="Delete Routine Status"/>								
PMA Number: 005845339								
PMA Number	NPA	Wire Ctr	Dist	Status	Pending Date	Dispatch Date	Complete Date	Type
005845339	205	221	1111	P	06/01/00			RTAP

Mgr: SMITH Tech: Presurvey Est: 6hr 0 min Work Address: TEST Work Desc: TEST	Supv: JONES Pre-Assign: N Maintenance Ctr: 900 Additional Tasks: N Task: 1 of 1
--	---

1 record found. Delete? no

**FIG. 23**

<input type="checkbox"/> Exclude Routine Status								
PMA Number: 005845339								
PMA Number	NPA	Wire Ctr	Dist	Status	Pending Date	Dispatch Date	Complete Date	Type
005845339	205	221	1111	P	06/01/00			RTAP

Mgr: SMITH	Supv: JONES
Tech:	Pre-Assign: N
Presurvey Est: 6hr 0 min	Maintenance Ctr: 900
	Additional Tasks: N
Work Address: TEST	Task: 1 of 1
Work Desc: TEST	

1 record found. Exclude? no

**FIG. 24**


LMOS Return Messages		
PMA Number	LMOS Time & Date	Complete Time & Date
000635924	06/01/00 06:15:00	06/01/00 07:47:15
0035226	created TTN 555555RTAP02	
000655119	06/01/00 08:37:15	06/01/00 11:56:43
0059935	created TTN 555555RTAP13	
000629881	06/02/00 14:22:56	06/03/00 09:33:40
0098662	created TTN 555555RTMISC11	

P- Print, F- Find, Q- Quit

**FIG. 25**

Search Criteria	
NPA:	<input type="text"/>
Wire Ctr:	<input type="text"/>
Dist #:	<input type="text"/>
Mgr:	<input type="text"/>
Supv:	<input type="text"/>
Hour From:	<input type="text"/> To: <input type="text"/>
Type:	<input type="text"/>
Work Code:	<input type="text"/>

**FIG. 26**



**FIG. 27**

